

Basic understanding of tertiary rolled in scale

Good example to explain the importance of temperature

Basic understanding of tertiary rolled in scale generation

Tertiary rolled in scale = f (strip surface temperature, roll surface roughness)

Strip surface temperature here generally means temperature after FSB till F3 or F4

Roll surface roughness means regular roughness, partial banding or small comet-like scoop.

Basic concept of tertiary rolled in scale

